

Under Review Notification

Raised By: Scott Cameron

Product #: RB6897875 (ROLLS ROYCE)

Date: Nov 29 2017

Product Name: FIXTURE - HOLDING, FUEL NOZZLE

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	APP Under Review	Product Specifications Under Review ("Bluefiles")		
RB6897875	RB6897875 Rev 3	Y	Y	N	N	Y	Y	N	17-771	Build to updated Rev D drawing
RB6897875-5	RB6897875 Rev 3	Y	Y	N	N	Y	Y	N	17-771	Build to updated Rev D drawing

Description of Issue:
 RB6897875:
 OEM drawing has modifications being done to -5 SOCKET
 Red Barn drawing calls up an off-the-shelf socket MSC 48725303 / PROTO J5208HS for -5. Off the shelf part does not meet OEM drawing dimensions.
 Epicor work instructions say to buy the off-the-shelf socket MSC 48725303 / PROTO J5208HS, and calls for manual lathe, manual mill, and bead blast ops
 Red Barn drawing will be updated to add machining dimensions and specifications for -5 SOCKET alterations to match OEM drawing and Epicor work instructions

Distribution:

VP Operations Director of Operations Director Quality Assurance Director of Engineering	Chief Engineer Engineering Project Managers Engineering Clerk Customer Support Manager	Production Engineers Production Planners Purchasing Manager Technical Support	Product Manager - Solutions Provider
--	---	--	--------------------------------------